Owner Name and Address: Geyser School Dist 58 103 3rd St E PO Box 70 Geyser MT 59447 Phone: (406) 735-4368

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
2303795	Geyser School Dist 58	103 3rd St E	Geyser	59447	(406) 735-4368	
		PO Box 70				

TankID/Alt TankID Status	T   _	nstalled Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently In Use	<b>4609</b> 7/1		Gasoline 2,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Safe Suction	8 0 E F G H 1 J K L	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging C Invent	tory Control E Vapor Monit	toring G Interstit, Dbl-Wall Monitor	I SIR	K Deferred	
	,	9		L Not Listed	

Report Generation Date: 7/3/2006 Page 1 of 36

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2308977	Malmstrom AFB A 3	US Highway 87	Geyser	59447	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	223	10/1/1992 13 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	ABCDEF.H.J.K.L B DEF.H.J.K.L	Yes Yes Yes Yes

## **Tank/Piping Release Detection Codes**

A Manual Tank Gauging C Invent	tory Control E Vapor Monit	toring G Interstit, Dbl-Wall Monitor	I SIR	K Deferred	
	,	9		L Not Listed	

Report Generation Date: 7/3/2006 Page 2 of 36

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2308986	Malmstrom AFB B 1	US Highway 87	Geyser	59447	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
4 / 03 Currently in Use	<b>224</b> 5.	5/2/1962 44 / No	Diesel 12,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Flexible Plastic Double-Walled	U.S. Suction	(ABCD@F@H)J&L (B D@F@H)@&L	Yes Yes Yes Yes

## **Tank/Piping Release Detection Codes**

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	T SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 3 of 36

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2308992	Malmstrom AFB B 7	US Highway 87	Geyser	59447	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	227 1	10/1/1992 13 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	8	Yes Yes Yes Yes

## **Tank/Piping Release Detection Codes**

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 4 of 36

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2308993	Malmstrom AFB B 8	US Highway 87	Geyser	59447	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	228	10/1/1992 13 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	ABCDEF.H.J.K.L B DEF.H.J.K.L	Yes Yes Yes Yes

## **Tank/Piping Release Detection Codes**

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred	
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed	

Report Generation Date: 7/3/2006 Page 5 of 36

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys	Fac I	Location Name	Location Street Address	<b>Location City</b>	Zip	Location Phone
23	308994	Malmstrom AFB B 9	US Highway 87	Geyser	59447	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	229	10/1/1992 13 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	ABCDEF.H.J.K.L B DEF.H.J.K.L	Yes Yes Yes Yes

## **Tank/Piping Release Detection Codes**

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	T SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 6 of 36

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2308995	Malmstrom AFB B 10	US Highway 87	Geyser	59447	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	230	10/1/1992 13 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	ABCDEF.H.J.K.L B DEF.H.J.K.L	Yes Yes Yes Yes

## **Tank/Piping Release Detection Codes**

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 7 of 36

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2308996	Malmstrom AFB B 11	US Highway 87	Geyser	59447	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	231	6/21/1989 17 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	ABCDEF.H.J.K.L B DEF.H.J.K.L	Yes Yes Yes Yes

## **Tank/Piping Release Detection Codes**

A Manual Tank Gauging C Invent	tory Control E Vapor Monit	toring G Interstit, Dbl-Wall Monitor	I SIR	K Deferred	
	,	9		L Not Listed	

Report Generation Date: 7/3/2006 Page 8 of 36

Owner Name and Address: Hobson School Dist 25 PO Box 410 Hobson MT 59452 Phone: (406) 423-5483

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2305904	Hobson School Dist 25	Central Ave	Hobson	59452	(406) 423-5483

TankID/Alt TankID Status	Tag Installed Numbe Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
3 / S3 Currently in Use	<b>1388</b> 8/18/1990 15 / N	Heating Oil 10,000	STI-P3 None	Flexible Plastic Double-Walled/Non-Corro	U.S. Suction	ABCD • F G H 1 J K L  B D • F • H 1 J K L	Yes Yes Yes Yes

## **Tank/Piping Release Detection Codes**

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 9 of 36

Owner Name and Address: Hill Oil Co PO Box 427 Hobson MT 59452 Phone: (406) 423-5343

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2306450	Hill Oil Co	N Main St	Hobson	59452	(406) 423-5343

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
5 / 05 Currently In Use	4745	4/1/1998 08 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	(ABC ● E F G H 1 J K L B D E F G H 1 ● K L	Yes Yes Yes Yes
6 / 06 Currently In Use	4746	4/1/1998 08 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	(ABC • EFGH ) J (K L) B D EFGH ) • (K L)	Yes Yes Yes Yes

## **Tank/Piping Release Detection Codes**

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	Not Listed

Report Generation Date: 7/3/2006 Page 10 of 36

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	<b>Location City</b>	Zip	Location Phone
2309104	Malmstrom AFB L 9	Road 400	Hobson	59452	

TankID/Alt TankID Status		stalled je/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	<b>243</b> 5/1/1	993 3 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	B DEF•H1JKL	Yes Yes Yes Yes

## **Tank/Piping Release Detection Codes**

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 11 of 36

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2309114	Malmstrom AFB M 8	Road 400	Hobson	59452	

TankID/Alt TankID Status	Y   F	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 02 Currently in Use	<b>244</b> 5/	1/1993 13 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	B DEF.H.J.K.L	Yes Yes Yes Yes

## **Tank/Piping Release Detection Codes**

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 12 of 36

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fa	c I	Location Name	Location Street Address	Location City	Zip	Location Phone
2309	000	Malmstrom AFB C 4	US Highway 87	Moccasin	59462	

TankID/Alt TankID Status	·	stalled ge/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	<b>235</b> 9/1/1	1992 3 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	B DEF•H1J&L	Yes Yes Yes Yes

## **Tank/Piping Release Detection Codes**

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 13 of 36

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fa	ac I	Location Name	Location Street Address	Location City	Zip	Location Phone
230	9001	Malmstrom AFB C 5	US Highway 87	Moccasin	59462	

TankID/Alt TankID Status	Y   F	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	<b>236</b> 9/	1/1992 13 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	B DEF.H.J.K.L	Yes Yes Yes Yes

## **Tank/Piping Release Detection Codes**

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 14 of 36

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2309002	Malmstrom AFB C 6	Road 239	Moccasin	59462	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	237	9/1/1992 13 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Safe Suction	ABCDEFOHIJKL  B DEFOHIJKL	Yes Yes Yes Yes

## **Tank/Piping Release Detection Codes**

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 15 of 36

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	<b>Location City</b>	Zip	Location Phone
2309003	Malmstrom AFB C 7	Road 239	Moccasin	59462	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 02 Currently in Use	238	9/1/1992 13 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	ABCDEFOHIJKL  B DEFOHIJKL	Yes Yes Yes Yes

## **Tank/Piping Release Detection Codes**

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 16 of 36

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2309115	Malmstrom AFB M 9	US Highway 87	Moccasin	59462	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 02 Currently in Use	<b>245</b> 5	5/1/1993 13 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	ABCDEF.H.J.K.L B DEF.H.J.K.L	Yes Yes Yes Yes

## **Tank/Piping Release Detection Codes**

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	T SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 17 of 36

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	<b>Location Phone</b>	
2309116	Malmstrom AFB M 10	US Highway 87	Moccasin	59462		-

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	246	5/1/1993 13 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	B         DEF●HIJKL	Yes Yes Yes Yes

## **Tank/Piping Release Detection Codes**

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 18 of 36

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2008978	Malmstrom AFB A 4	Road 427	Raynesford	59469	(406) 731-6163

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	<b>221</b> 6	/1/1992 14 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	ABCDEF.H.J.K.L B DEF.H.J.K.L	Yes Yes Yes Yes

## **Tank/Piping Release Detection Codes**

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 19 of 36

Owner Name and Address: Mountain View Coop 2200 Old Havre Highway Lincoln MT 59639 Phone: (406) 453-5900

Sys Fac I	Location Name	Location Street Address		Location City	Zip	Location Phone	
2303301	Kibbey Korner Truck Stop	US Highway 87 & Route 427		Raynesford	59469	(406) 738-4400	
		PO Box 197					

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / Currently in Use	0	/ No					ABCDEFGH1JKL B DEFGH1JKL	Yes No No No
2 / S10 Currently in Use	1030	9/1/1996 09 / Ye	Diesel 10,000	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plastic None	Pressurized	<pre></pre>	Yes Yes Yes Yes
5 / S09 Currently in Use	1029	9/1/1996 09 / Ye	Gasoline 10,000	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plastic None	Pressurized	ABCDEFGH	Yes Yes Yes Yes
6 / S08 Currently in Use	1028	9/1/1996 09 / Ye	Diesel 8,000	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGH ( ) & L • • EFGH ( ) & L	Yes Yes Yes Yes
7 / S07 Currently in Use	1027	9/1/1996 09 / Ye	Diesel 8,000	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plastic None	Pressurized	ABCDEFGHJJ&L • • • • • • • • • • • • • • • • • • •	Yes Yes Yes Yes
8 / S06 Currently in Use	1026	9/1/1996 09 / Ye	Gasoline 25,000	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plastic None	Pressurized	ABCDEF6H1J&L  • • EF6H1J&L	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 20 of 36

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2308974	Malmstrom AFB A 1	US Highway 87	Raynesford	59469	

TankID/Alt TankID Status	.	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	<b>222</b> 5/2	2/1962 44 / No	Diesel 12,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Flexible Plastic Double-Walled	U.S. Suction	ABCD@F@H]J&L B D@F@H]@&L	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 21 of 36

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1408988	Malmstrom AFB B 3	MT Highway 81	Stanford	59479	(406) 731-6167

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	163	8/1/1992 13 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	ABCDEF®HIJKL B DEF®HIJKL	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	T SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 22 of 36

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1408989	Malmstrom AFB B 4	MT Highway 80	Stanford	59479	(406) 731-6167

TankID/Alt TankID Status	· ·   _	nstalled Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 02 Currently in Use	<b>164</b> 9/1/	/1992 13 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	B DEF•H1J&L	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 23 of 36

Owner Name and Address: Shirley Woodhall PO Box 485 Stanford MT 59479 Phone: (406) 566-2203

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2301526	By Way Service Station	MT Highway 80 & US Highway 87	Stanford	59479	(406) 566-2203

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 06 Currently in Use	4410	9/1/1996 09 / No	Diesel 5,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Safe Suction	ABC●EFGHIJKL B DEFGHI●KL	Yes Yes Yes Yes
7 / 07 Currently In Use	4411	10/1/1998 07 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGHIJKL (O) (D) (E) (G) (H) (J) (L)	Yes Yes Yes Yes
8 / 08 Currently In Use	4412	10/1/1998 07 / No	Gasoline 5,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<pre>ABC●EFGHIJKL  ● ●EFGHIJKL</pre>	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 24 of 36

Owner Name and Address: Stanford School Dist 12 104 4th Ave S Stanford MT 59479 Phone: (406) 566-2265

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2301938	Stanford School Dist 12	104 4th Ave S	Stanford	59479	(406) 566-2265

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
3 / S3 Currently In Use	1893	10/9/1998 07 / No	Heating Oil 8,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	B DEF.H.I.K.	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 25 of 36

Owner Name and Address: Farmers Union Oil Co 1000 Smelter Ave Black Eagle MT 59414 Phone: (406) 453-2435

Sys Fac I	Location Name	Location Street Address	<b>Location City</b>	Zip	Location Phone	
2303303	Stanford Key Stop	MT Highway 80 & Main St	Stanford	59479		<u>-</u> '

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
4 / 04 Currently In Use	1031	7/6/1998 07 / No	Gasoline 2,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Safe Suction	A • • D • F G H I J K L  B D E F G H I • K L	Yes Yes Yes Yes
5 / 05 Currently In Use	1032	7/6/1998 07 / No	Gasoline 2,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Safe Suction	A • • D • F • H I J & L B D E F • H I • & L	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 26 of 36

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2308987	Malmstrom AFB B 2	MT Highway 80	Stanford	59479	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	225	9/1/1992 13 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	ABCDEF.H.J.K.L B DEF.H.J.K.L	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	T SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 27 of 36

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	<b>Location City</b>	Zip	Location Phone
2308991	Malmstrom AFB B 6	US Highway 87	Stanford	59479	

TankID/Alt TankID Status	N	nstalled Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	<b>226</b> 10/	1/1992 13 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	ABCDEFOHIJKL  B DEFOHIJKL	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	<b>K</b> Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 28 of 36

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2308997	Malmstrom AFB C 1	US Highway 87	Stanford	59479	(406) 731-3247

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	<b>232</b> 5	5/2/1962 44 / No	Diesel 12,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Flexible Plastic Double-Walled	U.S. Suction	$\begin{array}{cccccccccccccccccccccccccccccccccccc$	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	T SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 29 of 36

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2308998	Malmstrom AFB C 2	US Highway 87	Stanford	59479	

TankID/Alt TankID Status	Tag Install Numbe Age/A		Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	<b>233</b> 9/1/1992	Diesel No 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	(ABCDEF.H)J&C B DEF.H)J&C	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	T SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 30 of 36

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2308999	Malmstrom AFB C 3	US Highway 87	Stanford	59479	

TankID/Alt TankID Status	Tag Installed Numbe Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	<b>234</b> 9/11/1992 13 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	8 DEF . H . J . K L	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	T SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 31 of 36

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2309004	Malmstrom AFB C 8	US Highway 87	Stanford	59479	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 02 Currently in Use	239	9/1/1992 13 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Safe Suction	ABCDEF.H.J.K.L B DEF.H.J.K.L	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 32 of 36

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2309005	Malmstrom AFB C 9	US Highway 87	Stanford	59479	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	240	10/1/1992 13 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	(ABCDEF.H).). (B DEF.H).).	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2309006	Malmstrom AFB C 10	US Highway 87	Stanford	59479	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	241	9/1/1992 13 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	ABCDEF.H.J.K.L B DEF.H.J.K.L	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 34 of 36

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2309007	Malmstrom AFB C 11	US Highway 87	Stanford	59479	·

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	242	10/1/1992 13 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	ABCDEF.H.J.K.L B DEF.H.J.K.L	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 35 of 36

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2608990	Malmstrom AFB B 5	MT Highway 80	Stanford	59479	(406) 731-6167

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	258	9/10/1992 13 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Safe Suction	ABCDEF®HIJKL B DEF®HIJKL	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 36 of 36